

*Capacity governed by ultimate strength Values below heavy line require release strength higher than 35000 psi

$$f'_c = 5000 \text{ psi}$$

$$f_{pu} = 270,000 \text{ psi}$$